

S2995

List of reference symbols

1	substrate
2	trench
3	mask
5	selective oxide
6	HDP oxide
7	void